



DOUGLASS COMM LEAD WATER TEST RESULTS

May 16th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	DOUGLASS COMMUNITY CENTER AND POOL	5/24/2016	WS- 011562	Utility	1	In boiler room (water source)	WT-042916-11579- A	2.7	WT-042916-11579- B	< 1				
2	DOUGLASS COMMUNITY CENTER AND POOL	5/24/2016	WS- 011563	Kitchen	1	In kitchen Left	WT-042916-11580- A	18.2	WT-042916-11580- B	15.1	Filter will be installed and then retested			
3	DOUGLASS COMMUNITY CENTER AND POOL	5/24/2016	WS- 011564	Other	1	In kitchen (spray nozzle) Right	WT-042916-11581- A	9.3	WT-042916-11581- B	7.1				
4	DOUGLASS COMMUNITY CENTER AND POOL	5/24/2016	WS- 011565	Fountain	Ground Floor	Exterior adjacent to play ground Left Low	WT-042916-11582- A	< 1	WT-042916-11582- B	< 1				
5	DOUGLASS COMMUNITY CENTER AND POOL	5/24/2016	WS- 011566	Fountain	Ground Floor	Exterior adjacent to play ground Right High	WT-042916-11583- A	< 1	WT-042916-11583- B	< 1				
6	DOUGLASS COMMUNITY CENTER AND POOL	5/24/2016	WS- 011567	Fountain	Ground Floor	Exterior adjacent to basketball court Right High	WT-042916-11584- A	< 1	WT-042916-11584- B	< 1				
7	DOUGLASS COMMUNITY CENTER AND POOL	5/24/2016	WS- 011568	Fountain	Ground Floor	Exterior adjacent to basketball court Left Low	WT-042916-11585- A	< 1	WT-042916-11585- B	< 1				
8	DOUGLASS COMMUNITY CENTER AND POOL	5/24/2016	WS- 011569	Fountain	Ground Floor	Exterior adjacent to baseball field Right High	WT-042916-11586- A	< 1	WT-042916-11586- B	< 1				
9	DOUGLASS COMMUNITY CENTER AND POOL	5/24/2016	WS- 011570	Fountain	Ground Floor	Exterior adjacent to the baseball field Left Low	WT-042916-11587- A	< 1	WT-042916-11587- B	< 1				
10	DOUGLASS COMMUNITY CENTER AND POOL	5/24/2016	WS- 011571	Health Suite	1	In First Aid room	WT-042916-11588- A	< 1	WT-042916-11588- B	< 1				
11	DOUGLASS COMMUNITY CENTER AND POOL	5/24/2016	WS- 011572	Fountain	Ground Floor	Exterior, adjacent to men's locker room and pool	WT-042916-11589- A	< 1	WT-042916-11589- B	< 1				
12	DOUGLASS COMMUNITY CENTER AND POOL	5/24/2016	WS- 011573	Utility	1	In Boiler room pool	WT-042916-11590- A	69.9	WT-042916-11590- B	46.5	Non-drinking water source - Not accessible to children			

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.